

Connection Diagram

Method 1:

Transfer idrive adapter cable and LVDS cable on head unit, A# connected with C#, D# with B#. (Default method1)

DIP code setting:

6.5 inch: 00010000

8.8/10.25 inch: 00110000

Method 2:

Transfer LVDS cable on head unit, disconnect idrive cable, A# connect with B#.

DIP code setting:

6.5 inch: 00010000

8.8/10.25 inch: 00110000

Method 3:

Transfer idrive adapter cable and LVDS cable on head unit, L# connected with C#, D# with B#.

DIP code setting: 11100000

